Fast Ring Connectors

Drip Line (Thin and Medium Wall Thickness) Connectors and Tools



Product Features

High quality drip line connectors

Suitable for 6-25 mil (0.15-0.64 mm) seamless drip lines including D1000, D5000 and Hydrodrip

Features

High quality UV resistant construction

Large tightening nut for easy and quick installation

Advanced sealing mechanism

One ring for a wider range of wall thickness

Great value at a great price

When it comes to drip line connectors there are two things that matter most – ease of installation and reliability. Rivulis Fast Ring Drip Line Connectors live up to their name – FAST! In-field they are quick to install with a large, easy to tighten nut that fixes effortlessly to your drip line.

Once they installed, you can have the confidence that they will perform. Each Fast Ring Connector is designed for maximum adhesion. In addition, high quality UV resistant construction ensures that your connector will last season after season.

Fast Ring Connectors are suitable for all major brands of drip line that do not have a seam up to 25 mil (0.64 mm) wall thickness. Fast Ring Connectors are not suitable for Rivulis T-Tape, Ro-Drip or other drip tapes that feature a seam in their construction. For drip tapes with a seam such as T-Tape and Ro-Drip, use Rivulis Pro-Grip connectors.



Fast Ring Drip Tape and Flat Connectors (ex Pro-Grip) Rivulis

www.irrigationglobal.com



Fast Ring Drip Line Connectors and Tools

16 mm Diameter Drip Line Connectors

Image	Item Description	Product Information	Bag Quantity	Box Quantity	Item Reference
	Coupling fast ring 16mm		100	800	10105185
(Cto)	Adaptor barb 16mm x fast ring 16mm	Barb suitable for 40 mil (0.1 mm) and above	100	1,100	10105186
	Adaptor barb 20mm x fast ring 16mm	Barb suitable for 45 mil (1.1 mm) and above	50	800	10105188
	Start connector with gasket, from PVC or PE pipe, fast ring 16mm	Install into PVC with gasket by drilling a 15mm hole with DR-15 (101001353) and insert with R4-R, simple inserter (101003343)	100	800	10105189
	Gasket for start connector, from PVC or PE pipe, fast ring	Gasket for the start connector above (101051891)	100	3,600	10105188
	Start connector fast ring 16mm, from PE pipe	Install into PE by drilling a 12mm hole with DR-12 (101051466) and insert with R4-R, simple inserter (101003343)	100	1,200	10105189
	Line end fast ring 16mm		100	1,400	10105190
	Adaptor male threaded 1/2" x fast ring 16mm		100	900	10105190
0	Tee fast ring 16mm x 3/4" female threaded x fast ring 16mm		50	300	10105190
	Tee fast ring 16mm x 1/2" male threaded x fast ring 16mm		50	350	10105191
	Elbow fast ring 16mm x 1/2" male threaded		50	700	10105191
	Start connector for layflat fast ring 16mm	Install into layflat by cutting a 14mm hole with LFC14 layflat cutter (101001118) and insert with 10mm hex (101051919)	100	500	10105191
	Valve coupling fast ring 16mm x fast ring 16mm		100	300	10105191
Ro	Valve adaptor fast ring 16mm x male threaded 1/2"		50	400	10105191
Ro	Valve adaptor fast ring 16mm x male threaded 3/4"		50	350	10105191
C-CCC	Valve adaptor fast ring 16mm x barb 16mm	Barb suitable for 40 mil (1.0 mm) and above	50	350	10105193
	Valve start connector fast ring 16mm, from PE pipe	Install into PE by drilling a 12mm hole with DR-12 (101051466) and insert with R4-R, simple inserter (101003343)	50	400	10105191
	Valve start connector for layflat fast ring 16mm	Install into layflat by cutting a 14mm hole with LFC14 layflat cutter (101001118) and insert with 10mm hex. First insert the start connector and then thread the value.	50	300	10105191

Click for Ordering: Fast Ring Drip Tape and Flat Connectors (ex Pro-Grip) Rivulis

Fast Ring Drip Line Connectors and Tools

22 mm Diameter Drip Line Connectors Item Description Product Information Image Bag Box Quantity Quantity Coupling fast ring 22mm 50 450 Adaptor barb 20mm x fast ring Barb suitable for 45 mil (1.1 mm) and above 50 600 22mm Start connector with gasket, from Install into PVC with gasket by drilling a 15mm 600 PVC or PE pipe, fast ring 22mm hole with DR-15 (101001353) and insert with 100 R4-R, simple inserter (101003343) Gasket for start connector , from Gasket for the start connector above PVC or PE pipe, fast ring (101051880)100 3,600 Start connector fast ring 22mm, Install into PE by drilling a 12mm hole with 100 700 from PE pipe DR-12 (101051466) and insert with R4-R, simple inserter (101003343) Start connector XL fast ring 22mm Install into PE by drilling a 18mm hole with dr-700 100 18 (101028533) and insert with R4-R, simple inserter (101003343) Line end fast ring 22mm 100 800 Adaptor male threaded 1/2" x fast 50 550 ring 22mm Adaptor male threaded 3/4" x fast 50 500 ring 22mm Tee fast ring 22mm x 3/4" female threaded x fast ring 22mm 50 250 Tee fast ring 22mm x 1/2" male 250 50 threaded x fast ring 22mm Elbow fast ring 22mm x 1/2" male 500 50 threaded Start connector for layflat fast ring Install into layflat by cutting a 14mm hole with 50 400 22mm LFC14 layflat cutter (101001118) and insert with 10mm hex (101051919)

	with folling liex (101031919)			
Valve coupling fast ring 22mm x fast ring 22mm		50	250	101051898
Valve adaptor fast ring 22mm x male threaded 1/2"		50	300	101051901
Valve adaptor fast ring 22mm x male threaded 3/4"		50	250	101051902
Valve adaptor fast ring 22mm x barb 20mm	Barb suitable for 45 mil (1.1mm) and above	50	250	101051903
Valve start connector fast ring 22mm, from PE pipe	Install into PE by drilling a 12mm hole with DR- 12 (101051466) and insert with R4-R, simple inserter (101003343)	50	350	101051904
Valve start connector for layflat fast ring 22mm	Install into layflat by cutting a 14mm hole with LFC14 layflat cutter (101001118) and insert with 10mm hex. First insert the start connector and then thread the valve.	50	250	101051906

Rivulis.com Buy online: Fast Ring Drip Tape and Flat Connectors, Rivulis

Item

Reference

101051885

101051886

101051880

101051884

101051881

101051882

101051883

101051888

101051890

101051893

101051894

101051895

101051897

Fast Ring Drip Line Connectors and Tools

Fast Ring - Too	ls		
Image	Item Description	Product Information	Item Reference
	Drill Bit - 12 mm (DR – 12)	Suitable for PE. use for start connector fast ring 16mm (101051892) and 22mm (101051881)	101051466
	Drill Bit - 15 mm (DR – 15)	Suitable for PE or PVC. use for start connector with gasket, 16mm (101051891) and 22mm (101051880)	101001353
	Drill Bit - 18 mm (DR – 18)	Suitable for PE. use for start connector XL Fast ring 22mm (101051882)	101028533
STATION	Inserter for start connector	Used for inserting the gaskets into place	101003343
	14 mm Layflat cutter	Used for cutting layflat	101001118
	Layflat plastic driver hex 10mm for fast ring	Used to insert the layflat start connectors into hole cut into the layflat	101051919

Rivulis Pro-Grip Connectors	Rivulis Fast Ring Connectors	Rivulis Heavy Wall Connectors
Easy to install and ideal for both seam and non-seam drip tapes and drip lines up to 25 mil (0.64 mm) wall thickness	The economical solution for drip lines without a seam, up to 25 mil (0.64 mm) wall thickness	Unique triple barb connectors (available for many configurations) allows you to install drip line without the need for additional ratchet clamps. Suitable for all major brands of 30–47 mil (0.76– 1.2 mm) wall thickness drip lines.
Use with Rivulis T-Tape and Ro-Drip	Use with Rivulis D1000, D5000 and Hydrodrip	Use with Rivulis Hydrogol, HydroPC/PCND, D2000 and D5000

Shop Online: Fast Ring Flat Dripline and Tape Connectors, Rivulis

www.irrigationglobal.com



This literature has been compiled for worldwide circulation and the descriptions, photos, and information are for general purpose use only. Please consult with an irrigation specialist and technical specifications for proper use of products. Because some products are not available in all regions, please contact your local dealer for details. Rivulis Irrigation reserves the right to change specifications and the design of all products without notice.